Building Health Inspection Report

Frontwall Wall




Backwall Wall



Leftwall Wall



Rightwall Wall



Al-Based Risk Analysis

Al-Based Structural Crack Analysis:

Overall Average Score (out of 10): 9.6

- Frontwall Wall: 10.0/10

- Backwall Wall: 10.0/10

- Leftwall Wall: 10.0/10

- Rightwall Wall: 8.5/10

Severity Level: Low

Recommendation: Structure is likely healthy. No immediate action needed.