

# Building Health Inspection Report


## Frontwall Wall



## Backwall Wall



## Leftwall Wall



## Rightwall Wall



## AI-Based Risk Analysis

AI-Based Structural Crack Analysis:

Overall Average Score (out of 10): 9.6

- Frontwall Wall: 10.0/10

- Backwall Wall: 10.0/10

- Leftwall Wall: 8.5/10
- Rightwall Wall: 10.0/10

Severity Level: Low

Recommendation: Structure is likely healthy. No immediate action needed.