GetAutoSure

Report ID: GetAutoSure-PPI-20261028-1630
Scanned: 28 Oct 2026, 4:30 PM
Device: GetAutoSure OBD2 Scanner

Sample report — test-mode car with an example RTO record. Not a real vehicle.

PRE-PURCHASE INSPECTION REPORT

MARUTI SUZUKI SWIFT VXI

MH12AB1234 · Manufactured 2019 · PETROL

VERDICT

Buy with caution

Buyable, but go in with your eyes open — a few things are worth raising with the seller.

ENGINE HEALTH

100 /100

RED FLAGS	FAULTS FOUND	EST. REPAIR COST	FAIR VALUE
3	1	₹8,000–35,000	₹2.51 L–2.95 L
Need an answer	+ 1 developing	Tentative range	Before repairs

VEHICLE

Registration
MH12AB1234

VIN (from the car's computer)
XX9SAMPLEK0123456

Manufactured
Mar 2019

ODOMETER

Engine computer
84,210 km

Dashboard (entered at the car)
62,000 km

Scanned on
28 Oct 2026, 4:30 PM

WHAT WE CHECKED

Stored fault codes	✓ Clear
Hidden permanent codes	! Red flag
Developing (pending) faults	? Ask the seller
Codes cleared before the sale	! Red flag
Driven with warning light on	– Not reported
Engine pre-warmed	? Ask the seller
Odometer: dashboard vs computer	! Red flag
Chassis number matches RC	✓ Clear

Red flags

Signs something may have been hidden from you. Each needs an answer from the seller before you pay.

Fault codes were cleared recently

Only 18 km · 3 engine warm-ups · 40 min of running since the reset. Self-tests not finished yet: Catalyst.

ASK THE SELLER

Ask why they were cleared and what the fault was. Unless the car is nearly new, a reset just before a sale is a red flag.

Permanent fault code still stored

P0420 — this can't be erased with a scanner, and it's no longer in the normal fault list. It was likely cleared before the fault was fixed.

ASK THE SELLER

Ask what was repaired and for the invoice.

Dashboard km doesn't match the car's computer

Dashboard 62,000 km, engine computer 84,210 km — a gap of 22,210 km. It can mean the odometer was changed, or that the instrument cluster or engine computer was replaced.

ASK THE SELLER

Ask why, and ask for service records and invoices showing the km over the years.

Odometer history checks

What the car's own computer says about its distance and when its fault memory was last cleared.

Engine computer odometer	**84,210 km**
Dashboard odometer (entered at the car)	**62,000 km**
Dashboard vs computer	**Mismatch — 22,210 km apart**
Distance since fault codes were cleared	**18 km**
Engine warm-ups since codes were cleared	**3**
Engine running time since codes were cleared	**40 min**
Distance driven with the warning light on	**Not reported**

This is an odometer red-flag check, not a guarantee. A match means OBD shows no red flags; it can't rule out a rollback done on both the dashboard and the engine computer. Most cars made before about 2020 don't report their odometer over OBD at all — then service records are the best check.

RTO verification

The official registration record for this car, from the RTO.

Registration	**MH12AB1234**
Make / model	**MARUTI SUZUKI SWIFT VXI**
Fuel	**PETROL**
Colour	**PEARL ARCTIC WHITE**
Manufactured	**Mar 2019**
Registered on	**02-Apr-2019**
Registering RTO	**PUNE RTO**
Insurance	**ICICI Lombard, valid until 14-Mar-2027**
PUC valid until	**10-Jan-2027**
Fitness valid until	**01-Apr-2034**
Road tax valid until	**LTT**
Chassis number	**Matches the car's computer**

Check these against the seller's RC and what they told you about the car.

Major faults & estimated repair cost

Tentative Indian workshop ranges, not quotes — real prices vary by city, workshop and car. Get a quote before you negotiate on them.

Code	Fault	Type	Est. cost
P0420	Catalyst system efficiency below threshold (Bank 1)	**Hidden (cleared)**	₹8,000–35,000
P0171	System too lean (Bank 1)	**Developing**	Workshop quote
	Estimated total		**₹8,000–35,000**

Developing faults aren't in the total — the car hasn't confirmed them yet. "Workshop quote" means no reliable range fits that fault; it isn't free to fix. Several codes can share one cause, so the total can overstate the real bill.

Fair estimated value

Based on the IRDAI standard depreciation schedule — a rough estimate, not a verified valuation.

FAIR VALUE (BEFORE REPAIRS)

₹2.51 L – 2.95 L

What a car like this is worth in good order

AS IT STANDS (AFTER REPAIRS)

₹2.16 L – 2.87 L

Fair value less the repair estimate — a sensible offer range

58% depreciation over 7 years, adjusted for 62,000 km. IRDAI only publishes rates up to 5 years — beyond that this extrapolates, it isn't an official figure. Compare listings for the same model, year and km on CarDekho, Cars24 or OLX — they reflect your local market, this doesn't.

Worth asking the seller

Not signs of tampering — but good questions before you agree a price.

Developing fault not yet confirmed

P0171 — the car has noticed a problem once but hasn't turned on the warning light yet.

ASK THE SELLER

Ask the seller about it, or scan again after a longer drive.

Engine was already warm

Coolant was 85°C just 1 minute after starting. A warm engine can hide hard starting, smoke and rattles.

ASK THE SELLER

If you didn't just drive it yourself, ask to see it start from cold — ideally after standing overnight.

Before you pay

What an OBD scan can't see. Tick these off at the car.

- [ ] Chassis and engine numbers stamped on the car match the RC
- [ ] Service book and invoices support the odometer reading
- [ ] No loan on the car — the RC shows no hypothecation, or the bank's NOC and Form 35 are handed over
- [ ] No pending traffic challans (check on the Parivahan e-challan site)
- [ ] Insurance claim history — ask the insurer; a low No Claim Bonus can mean past claims
- [ ] Body: even panel gaps, no repaint or rust; no damp carpet or silt under the seats (flood damage)
- [ ] Cold start: starts easily, no smoke, steady idle
- [ ] Test drive: brakes, steering, clutch and gearbox, suspension noises, AC
- [ ] Tyres: even wear, enough tread, same make on each axle
- [ ] Transfer papers: Form 29 and 30 signed, original RC, insurance and PUC in hand

Not sure about something in this report? Talk to a real mechanic on WhatsApp from the GetAutoSure app, with this report in hand.

What this report doesn't cover

This report is built from the car's OBD2 data (engine, fuel and emissions) and, where checked, its RTO record. It doesn't cover accident repairs, bodywork, tyres, brakes, suspension, interior, or ABS/airbag/body-module codes, and it isn't a guarantee of the car's condition or history. Repair costs and fair value are tentative estimates. Scan profile: Test mode — used car, codes cleared by seller.

Generated by GetAutoSure · getautosure.com