



EMERALD

Chain Quality Problem

Insert metal removal or lifting while cutting




EMERALD

Copper wire Fixing





EMERALD

Chain joint Area Mismatch





Chipak Problem




EMERALD

Thumbling Balls inside the chain



EMERALD

Chain Not Soldered




EMERALD

Plating Issue



Under Cut (Metal not removed)




Punch Mark




EMERALD

3+1 Figaro chain but product 5+1 chain




Chain damage




EMERALD

Extra Metal



EMERALD

Holes



Improper Cutting

