PartSmith repair card

LEGO 2x4 brick reference

Family: custom

BEST EFFORT

Max error: 0.56 mm (pass: <= 0.5 mm, IoU >= 0.97)
top: IoU 0.995, Hausdorff 0.19 mm, mean 0.03 mm
side: IoU 0.980, Hausdorff 0.56 mm, mean 0.09 mm
Part tests: 11/11 passed
- top: refined in the photo frame by +0.02 deg, (+0.11, +0.20) mm on the mat
- side: refined in the photo frame by -0.29 deg, (-0.12, -0.10) mm on the mat
- top view (photo frame): IoU 0.995 (not gated), mean contour distance 0.03 mm (needs <= 0.15 mm), Hausd

Key dimensions

Length: 32.04 mm ± 0.12 [measured]
Width: 16.02 mm ± 0.11 [measured]
Thickness: 9.60 mm ± 0.30 [user stated]

Print settings (suggested)

PLA, 0.4 mm nozzle, 0.2 mm layers
4 walls, 40% infill, supports: no
Orientation: -Z: mounting face (Z=0) on the bed, as modelled

Repair passport

DETM7D

Broke again? Scan to reprint — your printer's clearance comes with it.

http://localhost:3000/p/DETM7D

Or type the id on the PartSmith site at /p/<id>. No new photos needed.