

## SVNIT Crash Data for TEST

### Accident Summary - 2032770066778899

|                         |                                                   |                              |                        |
|-------------------------|---------------------------------------------------|------------------------------|------------------------|
| <b>FIR/CSR Number :</b> | GJ012345006                                       | <b>FIR Date &amp; Time</b>   | 03-Jun-2032 : 08:00 PM |
| <b>Act</b>              | Indian Penal Code, 1860, Motor Vehicles Act, 1988 |                              |                        |
| <b>Section</b>          | Section 279; Section 338, Causing grievous hurt   |                              |                        |
| <b>State Rule</b>       | NA                                                | <b>Accident ID</b>           | 2032770066778899       |
| <b>Station Name</b>     | LIMBAYAT POLICE STATION                           | <b>Investigating Officer</b> | Hardik Pandya          |
| <b>Station Address</b>  | Limbayat, Surat, Gujarat, India                   | <b>Field Officer</b>         | Jigar Modi             |
| <b>District Code</b>    | 316                                               | <b>District Name</b>         | Surat                  |

#### Accident Details

|                                              |                                         |
|----------------------------------------------|-----------------------------------------|
| <b>Accident Date and Time</b>                | 03-Jun-2032 : 07:00 PM                  |
| <b>Reporting Date and Time</b>               | 03-Jun-2032 : 08:30 PM                  |
| <b>Landmark Name</b>                         | Limbayat, Near Chowk Bazar              |
| <b>Location Details</b>                      | Opp. Limbayat Municipality Office       |
| <b>Severity</b>                              | Grievous Injury                         |
| <b>Road Classification</b>                   | Urban Road                              |
| <b>Road Name / Street Name</b>               | Limbayat Main Road, Surat               |
| <b>Local Body</b>                            | Limbayat Urban Development Authority    |
| <b>Collision Type</b>                        | Vehicle to Animal                       |
| <b>Collision Nature</b>                      | Collision while avoiding                |
| <b>Initial observation of accident scene</b> | Animal on Road                          |
| <b>Traffic Violation</b>                     | Loss of Control                         |
| <b>Weather Condition</b>                     | Rainy / Wet                             |
| <b>Light Condition</b>                       | Street Light                            |
| <b>Accident Spot</b>                         | Residential Zone                        |
| <b>Visibility</b>                            | 30                                      |
| <b>Remedial Measures</b>                     | Animal intrusion barriers on road edges |
| <b>Property Damage</b>                       | Yes                                     |
| <b>Property Description</b>                  | Divider post damaged                    |
| <b>Approximate Damage Value</b>              | 15000                                   |
| <b>No of Vehicle(s) involved</b>             | 1                                       |

#### Number of Persons involved in the Accident

|               | Killed | Grievous Injury | Minor Injury | No Injury | Total |
|---------------|--------|-----------------|--------------|-----------|-------|
| <b>Driver</b> | 0      |                 |              |           | 1     |

|            |   |   |   |   |   |
|------------|---|---|---|---|---|
| Passenger  | 0 |   |   |   | 0 |
| Pedestrian | 0 |   |   |   | 0 |
| Total      | 0 | 1 | 0 | 0 | 1 |

## Vehicle Details

|                                     |                                                   |
|-------------------------------------|---------------------------------------------------|
| Vehicle Regn. No                    | GJ05KL2345                                        |
| Accused / Victim                    | Victim                                            |
| Previously Involved Accidents Count | 0                                                 |
| Vehicle Category                    | Motorised Fuel Vehicle                            |
| Reg.No Status                       | Known                                             |
| Hit & Run                           | No                                                |
| Vehicle Damage                      | Front Damage, Side Damage                         |
| Owner Name                          | NEHABEN PARMAR                                    |
| Owner Father Name                   | NA                                                |
| Owner Address                       | NA                                                |
| Vehicle Type                        | Motorcycle / Scooter                              |
| Load Category                       | Passenger                                         |
| Load Conditions                     | Empty                                             |
| Colour                              | SILVER                                            |
| Make & Model                        | Honda Motorcycle and Scooter India / Honda Activa |
| Engine Number                       | JF50E1234567                                      |
| Chassis Number                      | ME4JF503HF1234567                                 |
| Insurance Validity                  | 11-Feb-2034                                       |
| Fuel Type                           | Petrol                                            |
| Vehicle GVW                         | 108                                               |
| Seating Capacity                    | 2                                                 |
| Wheelbase                           | 1261                                              |
| Fitness Validity                    | NA                                                |
| Norms Description                   | BHARAT STAGE VI                                   |
| Brake Type                          | Combined Brake System                             |
| Condition of Brake                  | Satisfactory                                      |
| Damage Status                       | Front Damage, Side Damage                         |

## Driver Details

|             |                |
|-------------|----------------|
| Name        | NEHABEN PARMAR |
| Age         | 28             |
| Gender      | Female         |
| Nationality | Indian         |
| Education   | Graduate       |
| Occupation  | Teacher        |

|                                            |                 |
|--------------------------------------------|-----------------|
| <b>Driving License Type</b>                | Permanent       |
| <b>Driving License Status</b>              | Active          |
| <b>Non Transport DL validity</b>           | 20-03-2050      |
| <b>Seatbelt / Helmet</b>                   | Not Applicable  |
| <b>Drunk and Driving</b>                   | No              |
| <b>Cell Phone While Driving?</b>           | No              |
| <b>Injury Type</b>                         | Grievous Injury |
| <b>Severity</b>                            | Grievous Injury |
| <b>Blood Group</b>                         | A-              |
| <b>Previously involved accidents count</b> | 0               |

## Road Details

|                                           |                             |
|-------------------------------------------|-----------------------------|
| <b>Area Type</b>                          | Urban                       |
| <b>Road Classification</b>                | Urban Road                  |
| <b>Road Owning Agency</b>                 | Surat Municipal Corporation |
| <b>Type of Road Surface</b>               | Bituminous / Asphalt        |
| <b>Surface Condition</b>                  | Slippery (Wet)              |
| <b>Type of Carriageway</b>                | 2 Lane Undivided (2 way)    |
| <b>Road Width (in metre)</b>              | 6.5                         |
| <b>Accident Location Horizontal curve</b> | Straight Road               |
| <b>Speed Limit (in KMPH)</b>              | Below 40                    |
| <b>Road Markings</b>                      | Faded                       |
| <b>Road Sign Board</b>                    | Available - Non Reflective  |
| <b>Physical Divider / Barrier Type</b>    | Yes                         |
| <b>Type of Median</b>                     | Painted median              |
| <b>Pedestrian Infrastructure</b>          | Footpath available          |
| <b>Ongoing Road Work</b>                  | No                          |