

Transformer Inspection Report — XFMR-00261

Asset inspection record for transformer XFMR-00261, a 41.02 MVA unit manufactured by GE Vernova and installed in 2018 (8 years in service). The unit is connected to feeder feeder-037-0490 at substation sub-teresaburgh-037 and its current status is in_service.

Visual inspection findings: oil level and condition — clear, recently filtered. Bushings — light corrosion at flange. Cooling fans and radiators were operating normally. Grounding connections were verified intact. Inspection performed by a Field Engineer under weather conditions: high wind advisory.

SCADA alarm history for XFMR-00261 over the trailing twelve months shows 3 recorded alarms: ground fault (1), low oil level (1), voltage sag (1). 0 of these remain unresolved.

Thermal alarm count (0) is below the capacity-upgrade-review threshold. No loading study is required at this time.

Recommended follow-up: no action required; return to standard inspection rotation.