

## Job Card

---

Equipment ID: 1

Priority Level: High

Failure Probability: 0.78

Suggested Completion Date: 2024-10-15

Maintenance Tasks:

- High priority: Perform detailed inspection
- check for overheating
- and lubricate motor.