


Aircraft Defect Detection Report

Generated on: 2025-07-21 13:48:04

■ Inspection Snapshot:

This image shows detected defects outlined with green bounding boxes.



■ Detected Defects:

- Detected: Dent (Box 1)
- Detected: Paint-off (Box 2)

■ Defect Summary:

- Dent: 1
- Paint-off: 1

■ Risk Assessment:

■ No critical risks detected.