

# Aircraft Defect Detection Report

Generated on: 2025-07-21 13:49:34

## ■ Inspection Snapshot:

This image shows detected defects outlined with green bounding boxes.



## ■ Detected Defects:

- Detected: Paint-off (Box 1)

## ■ Defect Summary:

- Paint-off: 1

## ■ Risk Assessment:

■ No critical risks detected.