


# Aircraft Defect Detection Report

Generated on: 2025-07-21 14:13:20

## ■ Inspection Snapshot:

This image shows detected defects outlined with green bounding boxes.



## ■ Detected Defects:

- Detected: Crack (Box 1)
- Detected: Crack (Box 2)
- Detected: Paint-off (Box 3)
- Detected: Crack (Box 4)

## ■ Defect Summary:

- Crack: 3
- Paint-off: 1

## ■ Risk Assessment:

■ **Critical maintenance required!** Severe defects like cracks or missing-heads were detected.