

Aircraft Defect Detection Report

Generated on: 2025-07-21 13:45:53

■ Inspection Snapshot:

This image shows detected defects outlined with green bounding boxes.



■ Detected Defects:

- Detected: Paint-off (Box 1)

■ Defect Summary:

- Paint-off: 1

■ Risk Assessment:

■ No critical risks detected.