# Aircraft Defect Detection Report

Generated on: 2025-07-21 14:10:39

## ■ Inspection Snapshot:

This image shows detected defects outlined with green bounding boxes.



#### **■** Detected Defects:

• Detected: Paint-off (Box 1)

# ■ Defect Summary:

• Paint-off: 1

## ■ Risk Assessment:

■ No critical risks detected.