

Aircraft Defect Detection Report

Generated on: 2025-08-27 19:32:54

■ Inspection Snapshot:

This image shows detected defects outlined with green bounding boxes.



■ Detected Defects:

- Detected: Dent (Box 1)

■ Defect Summary:

- Dent: 1

■ Risk Assessment:

■ No critical risks detected.