

# ROAD DAMAGE INSPECTION REPORT

Generated by Pothole Detection AI System  
Report ID: A4578112 | Date: 15 March 2026, 16:01

## 1. EXECUTIVE SUMMARY

**Location:** Rajkot

**Total Potholes Detected:** 4

**Overall Road Status:** DAMAGED — Repair recommended soon

**Cumulative Damage Score:** 8.05

**Average Pothole Score:** 2.01

## 2. SEVERITY BREAKDOWN

| Severity        | Count | % of Total | Color Code |
|-----------------|-------|------------|------------|
| HIGH (Deep)     | 1     | 25%        | ■ Red      |
| MEDIUM (Medium) | 2     | 50%        | ■ Yellow   |
| LOW (Shallow)   | 1     | 25%        | ■ Green    |

## 3. DETAILED POTHOLE LOG

| # | Severity | Depth   | Area (m²) | Score | Source | Detected At      |
|---|----------|---------|-----------|-------|--------|------------------|
| 1 | MEDIUM   | Medium  | 0.67      | 1.33  | IMAGE  | 2026-03-15 16:01 |
| 2 | LOW      | Shallow | 0.13      | 0.13  | IMAGE  | 2026-03-15 16:01 |
| 3 | MEDIUM   | Medium  | 0.96      | 1.91  | IMAGE  | 2026-03-15 16:01 |
| 4 | HIGH     | Deep    | 1.56      | 4.68  | IMAGE  | 2026-03-15 16:01 |

## 4. RECOMMENDATIONS

- **URGENT:** 1 deep pothole(s) detected — immediate patching required. Enforce 20 km/h speed limit.
- **SOON:** 2 medium-severity pothole(s) — schedule repair within 2 weeks. Limit speed to 40 km/h.
- **MONITOR:** 1 shallow pothole(s) — include in next routine maintenance cycle.

Report auto-generated by Pothole Detection AI System. For official use by road authorities only.