



CUTTING INSPECTION REPORT

Doc. No: AE-QA-IR-FCG-DF02

Rev. No: 00

Date: 19/03/2026

CUSTOMER :	Vestas	Inspection Date	19/06/2026
PART / DRAWING NO :	29314225-6	Shift	day
PART DESCRIPTION :	DOOR WELD SUPPORT BOTTOM		

No diagram attached

Sl. No	Descriptions	Specifications (mm)	Actual Dimensions (mm)				
1	Overall length	1180-2	1190				
2	Width 1	50 +/- 1	40				
3	Width 2	34 - 1	34				
4	Distance 1	370 - 1	370				
5	Distance 2	440 +/- 1	330				
6	Distance 3	170 +/- 1	100				
7	Hole Diameter	7 +/- 0.5	6				
8	Hole Distance	25 +/- 1	25				
9	Radius	2xR4	22				
10	Angle	45°	30				
11	Distance 4	2x10	20				



CUTTING INSPECTION REPORT - OBSERVATIONS

Visual observation: Inspector Observation | Manager Observation

Disposition remarks:
Inspector Remarks | Manager Remarks

QA

Reviewed By:

A

Suresh_inspector

Hi