quickler

Demo Firm

Site Safety Inspection
Monday 2 November 2026, 13:49
Philip Ross

Bell Street, London NW1 · Shared view-only link

LOCATION

Bell Street
London
NW1

51.5226° N, 0.1683° W
9C8VF27G+CJ London

9.8°C
Clear Sky
↓3.7° ↑10.3°
Wind 6 mph W
Humidity 80%
Sunrise 07:22 · Sunset 16:27

⚠ To do list

93%

4

- Clear the back fire exit of boxes and trolleys immediately.
- Replace the out-of-date eyewash contents.
- Remove the extension lead trailing across the corridor, a trip hazard.
- Apply a unique identification number to the stepladder in the store.

Audit name

Site Safety Inspection

Audit information

Audit details

Site safety inspection.

Company Name

Demo Firm

Location

Bell Street, London NW1

Audit results

Audit notes

Everything else is fine, according to the inspector.

Fire Safety Criteria

Issue

Back fire exit is blocked, so this section has a fault.

Fire Safety - Alarm: Means of raising alarm available and unobstructed

Yes

Are fire exit routes free from obstructions

No

Back fire exit has been blocked with boxes and trolleys and needs clearing immediately.

Main fire exit is fine.



Internal fire doors self close and fully latch onto the door catch (if fitted), not propped open, open outward, unobstructed

Yes

Door closes and latches.

Fire Safety - Fire Fighting Equipment

OK

Appropriate extinguishers readily available

Yes

Extinguishers in service (12 monthly)

Yes

Extinguishers are in date.

Seal/tag in place

Yes

Service tag from gmc on the left extinguisher, with stickers and hanging tags attached to both extinguishers.



Extinguishers unobstructed

Yes

Fire Safety - Fire Log Book

OK

Fire log book available

Yes

Weekly checks completed

Yes

Emergency lighting checks carried out

Yes

Fire Safety - Signs

OK

Assembly points

Yes

Evacuation poster

Yes

Exit doors “Keep Clear”

Yes

Fire exit door with a ’DO NOT BLOCK FIRE EXITS’ sign above the push bar.

Outdoor fire exit door with ’FIRE EXIT / Do Not Block’ signs on the wall and the door.





Fire Extinguisher signs

Yes

First Aid - Signs

OK

1st Aiders identified

Yes

First aid kit locations clearly identified

Yes

First aid kit cabinet marked with a 'First Aid Kit' sticker.

Safety equipment

Issue

First Aid kits available

Yes

First aid kit is present and in a green wall-mounted cabinet.



Eye wash stations available and contents in date

No

Eyewash contents are out of date.

Burn kit available and contents in date

N/A

AED available? If so, is the serviceable indicator showing it is in a fit condition

N/A

First Aid - Kits Contents

OK

A few bandages are missing from the first aid kit.

Actual contents – Vs – Contents List

Yes

First aid contents in date

Yes

First aid kit is in date.

Lighting Criteria

OK

Internal lighting sufficient for normal working, operational, clean and in good condition

Yes

External lighting sufficient for normal working, operational, clean and in good condition

Yes

Localised lighting operational where fitted

N/A

Surface Conditions Criteria

OK

Roads: adequate marking, good condition

Yes

Outdoor paths, walking areas and steps in good condition

Yes

Walking routes and surfaces

Issue

Car park: Identified walking routes clear, good condition, speed restrictions

Yes

Pavements in good condition

Yes

Corridors and stairs unobstructed, good condition

No

An extension lead is trailing across the corridor, a trip hazard.

Workshops, Offices, Amenities and Welfare

OK

Hot and Cold Water available

Yes

Seating/Furniture/Working Benches in good condition

Yes

Floors in good condition

Yes

Acceptable noise levels

Yes

Cleanliness good

Yes

Heating/Temperature available and within tolerance

Yes

Ventilation: Available supply of fresh air

Yes

Smoking restrictions applied

Yes


Toilet facilities clean

Yes

Toilets are clean.

Electrical condition: Cables, plugs, sockets, panels, etc. in good condition, not overloaded, HV Panels locked

Yes



Electrical Criteria

OK

Portable appliances clearly identified with current test date

N/A

Signs

Yes

Stacking and Storage

OK

Height and Stability

Yes

Racking

N/A


Steps and Ladders

Issue

Unique identification number

No

Stepladder in the store has no ID number.



Condition

N/A

Miscellaneous

OK

Temporary Safety Notices

Yes

Storage Tanks

N/A

Hazardous substances clearly labelled and stored as recommended, with SDS and CoSHH assessment available

N/A



Plant and Equipment

N/A

Plant and equipment free from physical defects

N/A

Plant and equipment guards available, in good condition, fitted and used

N/A

Plant and equipment controls in normal operation, with emergency stops and isolation switches clearly identified

N/A

Movable plant (MEWPs, forklifts, pallet trucks, etc.) in good condition, operated safely, and operated by a competent operator

N/A

Manual Handling

OK

Manual Handling Operations: correct posture observed, excessive loads not being carried or handled, repetitive handling considered, and operatives trained

Yes

Manual Handling Loads: not too heavy, no sharp edges, and hot/cold considered

Yes

Manual Handling Environment: space allows good posture, and floors are even, non-slip, and stable

Yes

Manual Handling Aids: equipment in use where applicable, in good condition, and operatives trained

N/A

Documentation

OK

Health and Safety Policy Statement posted on the notice board and current

Yes

Safety Committee Minutes posted on the notice board and current

Yes

Health and Safety Law Poster posted on notice board and completed correctly

Yes

Health and safety law poster is present.

Third Parties

OK

Have any third parties onsite provided suitable RAMS for the works being undertaken	Yes
Have all third parties attended site-specific induction	Yes
Where applicable, has a permit to work been issued	Yes
Has the permit to work been completed correctly	Yes
Are third parties working within the permit	Yes
Are third parties working safely with workers wearing appropriate PPE and suitable segregation	Yes