





### **Technical Report**

TR150569

16-Jan.-2018

-		
_	ro	

#### Canez Power Division S.A.

**Electrical Motor- Rewinding Section** +509 2811 3669

team@canezgeneration.com

#### To:

#### Acierie D'Haiti S.A

Maintenance Manager +509 4896 2156

mrdgier@gbgroup.com

### 1. Motor Receive.

Date In:	February 16, 2018	
Description:	4 Electrical motors	
Fault:	They're burned	
Delivery	Feb. 26 <sup>th</sup> 2018 Delivery by Wendy Team	

### 2. Repair

# **Opening process**









Received

Rotor

Stator burned


Covers

Stator burned

## **Repair Process**











Ready to wire

Stators rewinding Rewinding ongoing Bearings Changed

**Painted** 

#### 3. Final Comments

Received 4 electrical motors 1 stator burned and 3 complete. Job done: rewinding, both bearings changed and paint them .

### 4. Warranty Tag

- 15145 / 15147 / 15146
- 90 days warranty

**Technical Report**