





Technical Report

TR150565

12-Jan.-2018

| г | - | |
|---|-------|----|
| • | ım | 10 |

Canez Power Division S.A.

Electrical Motor- Rewinding Section +509 2811 3669

team@canezgeneration.com

To:

Acierie D'Haiti S.A

Maintenance Manager +509 4896 2156

mrdgier@gbgroup.com

1. Motor Receive.

| Date In: | Jan.12 th ,2018 | |
|--------------|--|--|
| Description: | 1 electrical motor 60hp | |
| Fault: | Need to repair , cause it's burned | |
| Delivery | Jan.17 th ,2018 by Sonson (wendy) | |

2. Repair

Opening process



Received disassembled

Repair Process











Start rewinding

Rewinding ongoing Oven

Motor assembled

Painted

3. Final Comments

Received complete but came from Acierie D'Haiti disassembled, found stator wires burned Then only rewinding and painted.

4. Warranty Tag

- 15152
- 90 days warranty