

Technical Report

TR150562

3-Jan.-2018

From:

Canez Power Division S.A.
Electrical Motor- Rewinding Section
+509 2811 3669
team@canezgeneration.com

To:

Epidor
Tel: +50937010118 / 37353476
thierryattie@gmail.com

1. Motor Receive.

Date In:	Jan3rd 2018
Description:	2 electrical motors (2.2 kw /5hp)
Fault:	Need to rewire.
Delivery	Jan.25 th 2018, by Johnny (Epidor)

2. Repair

Opening process



Received



Bearings issues



Stators burned




covers issues

Repair Process



Stator ready



Rewinding



Oven



Covers repaired



Bearings changed



Paint

3. Final Comments

Received these electrical motors complete, found wires burned then rewinding, bearings changed, covers repaired and painted.

4. Warranty Tag

- 15150/15151
- 90 days warranty