



Technical Report

TR150564

12-Jan.-2018

From:

Canez Power Division S.A.
Electrical Motor- Rewinding Section
+509 2811 3669
team@canezgeneration.com

To:

Sejourne S.A.
Tel:2813 0225 / 36010113
sejournesa@yahoo.com

1. Motor Receive.

Date In:	January 12 th , 2018
Description:	1 electrical motor 90kw
Fault:	Need to repair cause it burned
Delivery	January 23 rd , 2018 by Billy with the small crane

2. Repair

Opening process



Received



Cover back missed



Rotor



Stator burned

Repair Process



Stator ready



Rewinding



From the Oven



Bearings good



Ready

3. Final Comments

Received this electrical motor complete, but back cover missed. Found wires burned, then rewinding, cleaned and put grass in both bearings only: Also covers are good.

4. Warranty Tag

- 15141
- 90 days warranty