





## **Technical Report**

TR150566

16-Jan.-2018

From:

Canez Power Division S.A.

**Electrical Motor- Rewinding Section** +509 2811 3669

team@canezgeneration.com

To:

**Santo Blocs** 

Santo 25, Carrefour Marassa

Tel: (+509)3424 8470 / 2943 4870 /37019466

#### 1. Motor Receive.

Date In:	Jan 16 <sup>th</sup> .2018
Description:	2 electrical motor 25 hp / 20 hp
Fault:	This 25 hp need maintenance and the 20 hp found wires stator burned.
Delivery	1 at Jan.8 <sup>th</sup> and the other Feb.7 <sup>th</sup> 2018 by Santo Blocs Team.

### 2. Repair

## **Opening process**



Receiv ed 1 stator burned



Need to repair



Both bearings in 1 rotor

## **Repair Process**



Rewinding



Oven







Bearings changed cover repaired Paint

## 3. Final Comments

Received two electrical motors complete: the 25 hp is the maintenance is done and the 20 hp stator found burned ,both bearings changed , 1 cover got repaired .

# 4. Warranty Tag

- 15149 / 15142
- 90 days warranty

**Technical Report**