CLAIMSIGHT AI | SIU Forensic Investigation Report

STATUS: INVESTIGATION_COMPLETED
REF: CLM-2026-002

CLAIM SUMMARY: Rear Collision with Unexplained Front-Left Wing Damage
Date of Loss: 2026-03-12 at 21:15:00 | **Location:** Outer Ring Road flyover, Marathahalli, Bengaluru
Accident Type: Reported Single-Point Rear Impact | **Claimed Damage:** INR 82,000.00
AI Investigation Priority Score: 78.4/100 (HIGH)

1. Vehicle & Coverage Information

Insured Vehicle	2023 Hyundai Creta SX	Registration No	KA-05-NB-9812
Chassis / VIN	MALC481CLPM019284	Color / Body	Polar White (SUV)
Policy Number	POL-HYU-2025-4190	Coverage Type	Comprehensive
Sum Insured	INR 1,450,000.00	Compulsory Deductible	INR 2,000.00

2. Forensic Evidence Inventory & Cryptographic Hashes

ID	Evidence Name	Modality	Source	SHA-256 Fingerprint
EVD-002-1	rear_creta_dent.jpg	IMAGE	Claimant Smartp...	91a8c3e411b98a7281...
EVD-002-2	front_left_fender_damage....	IMAGE	Bodyshop Intake	44b82d718a245582f6...
EVD-002-3	claimant_first_statement....	STATEMENT	Intake Audio Tr...	f6e729a73e4492b118...
EVD-CLM-2026-002-OFFICIAL	official_police_gd_GD-002...	DOCUMENT	Official Police...	7d8a9b0c1e2f345678...

3. Cross-Modal Inconsistencies & Contradictions

[CONFLICT] Contradiction (Severity: High)

Details: Claimant statement declares zero frontal contact and sole rear impact, yet front-left fender and headlamp sustained heavy structural crumple and distinct two-tone paint transfer.

Materiality: Material - Front damage accounts for ■52,000 of ■82,000 estimate.

Recommended Resolution: Inspect flyover median crash barrier for corresponding blue/yellow paint scrapings.

[CONFLICT] Contradiction (Severity: Critical (Priority Reference #1))

Details: PRIORITY REFERENCE #1: Consumer file narrative claims 'A speeding delivery truck struck my car from behind while slowing down for flyover tr...', whereas Official Police General Diary (GD-002/2026 - Indiranagar Traffic Police Station) records dynamic moving collision with conflicting damage locus and driver divergence at scene.

Materiality: Fundamental (Primary Reference) - Direct factual mismatch between consumer sworn declaration and official police station record.

Recommended Resolution: Request certified Station GD folio from Indiranagar Traffic Police Station and examine attending officer.

4. Multimodal AI Analysis & Incident Reconstruction

4.1 Computer Vision & Damage Decomposition (YOLOv8 Neural Detection):

YOLOv8 Neural Model	YOLOv8-DamageDetect v3.2	Detection Confidence	92% Neural Precision
Primary Damage Zone	REAR Structural Assembly	Spatial Alignment	Corroborated with Narrative
Localized Component	Rear Lower Bumper & Reflector Cluster	Damage Classification	Direct Shunt Plastic Fracture
Neural Bounding Box	X:176 Y:240 W:463 H:264	Vision Telemetry Source	Consumer Exterior Photograph

4.2 Multimodal Sensor & Evidence Fusion Matrix:

Evidence Modality	Source / Asset	Observed Content / Signal	Cross-Modal Assessment
Consumer Declaration	Claimant Intake Notice	A speeding delivery truck struck my car from ...	Primary First Notice
Exterior Photography	Forensic Image Upload	Deformation on Rear Lower Bumper & Reflector Cluster (REAR)	Corroborated with Narrative
Official Police GD Extract	Indiranagar Traffic Po	Station General Diary extract records two-veh...	Divergence Flagged
Bodyshop Quote	Financial Repair File	INR 82,000.00 repair line items	Verified vs OEM Benchmark

4.3 Multi-Hypothesis Accident Reconstruction:

Secondary Rebound Collision with Guardrail — *Support Level: Moderate Support (Prob: 48%)*
• **Summary:** Vehicle was rear-ended, driver panicked and swerved left into the bridge barrier.
• **Assumptions:** Driver omitted barrier contact due to fear of contributory negligence

Pre-Existing Frontal Damage Bundling — *Support Level: Strong Evidence of Divergence (Prob: 52%)*
• **Summary:** Front fender damage occurred prior to this incident and is improperly bundled into this rear-end claim.
• **Assumptions:** Paint transfer colors do not match any vehicle involved in the rear collision

H1: Primary Rear Impact Followed by Secondary Barrier Rebound — *Support Level: Moderate Support (Prob: 48%)*
• **Summary:** Vehicle was rear-ended, causing driver to swerve into the bridge safety guardrail.
• **Assumptions:** Driver experienced sudden rotational inertia after rear bump

H2: Pre-Existing Frontal Damage Bundled into Rear Claim — *Support Level: Strong Evidence of Divergence (Prob: 52%)*
• **Summary:** Front fender and headlamp were damaged in a separate prior unnotified incident.
• **Assumptions:** Rear impact energy was insufficient to deform front crumple zones

5. Ranked Next-Best-Evidence Forensic Requests

Rank	Recommended Action	Target Uncertainty	Priority	Score
#1	Inspect Marathahalli Flyover CCTV F...	Validates whether third-party heavy...	High	1.57
#2	Request Front Impact Absorber & Cha...	Differentiates secondary barrier re...	Critical	2.29

6. Indicative Settlement & Traceable Calculation

Claimed / Quoted Repair Cost	INR 82,000.00
SIU Verified Eligible Repair	INR 30,000.00
Less: Compulsory Deductible	- INR 2,000.00
Less: Plastic / Paint Depreciation	- INR 4,500.00
Less: Salvage Recovery Allowance	- INR 800.00
INDICATIVE SETTLEMENT PAYOUT	**INR 22,700.00**

Human Investigator Decision: APPROVED
Investigator Notes: Multimodal evidence, hypotheses, and Next-Best-Evidence recommendations under active SIU review.
Responsible Investigator: Chief Compliance Officer