



ARS QUALITY SERVICES

DAILY INSPECTION REPORT

Servicio: xxxxxxxx

LOCATION: Hierbabuena

AFFILIATE: asdasdas hola

QTY AUTHORIZED: 900

WORK DESCRIPTION: Abolladura

REMAINING PCS: 295

PART NUMBER & PART NAME: Cuchufleta33

GRAND TOTAL						
	INSP.	OK	RWRK	NOK	MAN/HRS	PART NUMBER
	605	566	7	48	8	Cuchufleta33

Fallas				
rayadura	Abolladura	doblado	despintado	carbonizado
25	20	2	1	0

Fallas

