

Type / Maker















 $\boxtimes$ 

inprecasa@inprecasa.com

Date:	Ship / Unit:	IMO:	Call sign:	Certificate:
08/05/2025	DACIL	9427445	CQVC	26413/2025

## **WATER MIST FIRE FIGHTING SYSTEM CERTIFICATE OF RE-INSPECTION**

INPRECASA, Authorized by Spanish Ministerio de Industria y Energía for Fire Systems service, recharge and hydro test to pressurised cylinders on ships and marine installations, certify:

Type / Maker	N/A						
Manufact.Date	2005						
Number of Tank/Capacity	1 Tank 24000 ltrs						
Number of Pump	1						
Distribution lines:	9						
Areas covered:	MAIN ENGINE 1 to 2 / /DIESEL GEN,1 to 3 // BOILER 1 to 2// SEPARATOR // INCINERATOR						
Description of Inspection / To	ests Carried out						
Release system and distribution valves secured			Not Carried				
recease system and distributio	iii vaives secured		out	Not applicable	OK		
Water tank checked	Ti valves secured		out	Not applicable	OK		
<u> </u>	in valves secured		out	Not applicable	OK		
Water tank checked	in valves secured		out	Not applicable	OK		
Water tank checked By weighting	in valves secured		out	Not applicable	OK  S  S  S  S  S  S  S  S  S  S  S  S  S		
Water tank checked By weighting By liquid level	in valves secured			Not applicable	OK 		
Water tank checked By weighting By liquid level By level alarm	in valves secured			Not applicable	OK  S  S  S  S  S  S  S  S  S  S  S  S  S		
Water tank checked By weighting By liquid level By level alarm Test running pump Local functional test Remote functional test (pump a	and engine control room)			Not applicable	OK  S  S  S  S  S  S  S  S  S  S  S  S  S		
Water tank checked By weighting By liquid level By level alarm Test running pump Local functional test Remote functional test (pump a	and engine control room)			Not applicable	OK  SI  SI  SI  SI  SI  SI  SI  SI  SI  S		
Water tank checked By weighting By liquid level By level alarm Test running pump Local functional test Remote functional test (pump a	and engine control room)			Not applicable	OK  S  D  S  S  S  S  S  S  S  S  S  S  S		

The results of the above test are considered correct, being the system in working order for the good operation.

 $\boxtimes$ 

We certify this to whom it may concern in Santa Cruz de Tenerife, May 8th, 2025



Working pressure Covering all areas Main alarm

Nozzles free of obstacles

Inspection date labels attached

Switch off power supply to Main Control Panel Distribution lines and nozzles visually inspected

mist system by flowing water through the nozzles

All instruction plates on installation inspected

Test a minimum of one section in each open head water

INPRECASA TENERIFE C/ Fonseca 10-12 38320 La Laguna - Tenerife

Tfno. (+34) 922 650 131 Fax (+34) 822 201 271



## **INPRECASA LAS PALMAS**

C/ Pinillos Izquierdo Nave 2 Puerto de Las Palmas 35008 Las Palmas de Gran Canaria Tfno. (+34) 627 575 272 Fax (+34) 822 201 271