Observation Date	2024-10-02										
Observer	John Davis										
Company Observed	Summit Construction										
Location (CWA)	1000		2000		3000		4000		8000	X	
	5000		5900		6000		7000		OSLD		
Shift	**Day**	X		**Night**							
Timesheet #	25489			**Employee #**	7852						

Breaking Containment – Life Saving Action

Safe [S] At Risk [R] Imminent Hazard [I] N/A [N]

		S	R	I	N
01	Has the location to be cut or opened been visibly marked?			X	
02	Work has been authorized to begin (e.g.– Line Break Permit)			X	
03	Nearby work activities has no potential ignition sources or conflict with work scope (e.g. hot work)			X	
04	Exclusion zone (e.g. barricade) is in place.		X		
05	There is clear means of communication with the equipment operator	X			
06	Workers positioned outside line of fire			X	
07	Spill containment plan in place			X	
08	Energy sources isolated and secured			X	

CCZJV Expectation Questions	**Yes**	**No**	**N/A**
Has positive feedback provided?	X		
Has the job been stopped in the event of an imminent hazard?		X	
Has an investigation been conducted?			X
Have corrective actions been taken?			X

Comments:

Safety measures were strictly followed.

Observation Date	2024-10-01										
Observer	Luis Gomez										
Company Observed	Hernandez Builders										
Location (CWA)	1000	X	2000		3000		4000		8000		
	5000		5900		6000		7000		OSLD		
Shift	**Day**				**Night**	X					
Timesheet #	36781				**Employee #**	14589					

O&I Confined Space – Life Saving Action

Safe [S] At Risk [R] Imminent Hazard [I] N/A [N]

		S	R	I	N
01	Proof of Training for CSE Duties (e.g. HH Stickers)			X	
02	Does the crew have a valid confined space permit?				X
03	Reliable communication is available for an Emergency (e.g. Hole Watch)				X
04	CSE Attendant monitoring entrant status and can communi-cate with entrants				X
05	Access/egress entry ways clear of obstructions?				X
06	Controls to prevent unauthorized access (e.g. Barricades, attendant, signs) are in place?			X	
07	Fire extinguisher located near entry point?			X	
08	Does the crew maintain an access/egress record?			X	

CCZJV Expectation Questions	**Yes**	**No**	**N/A**
Has positive feedback provided?			X
Has the job been stopped in the event of an imminent hazard?		X	
Has an investigation been conducted?	X		
Have corrective actions been taken?	X		

Comments:

Improvements needed in communication.

Observation Date	2024-09-30
Observer	Maria Hernandez
Company Observed	Queen's Contracting

Location (CWA)										
	1000		2000		3000		4000		8000	
	5000		5900		6000		7000	X	OSLD	

Shift	**Day**		**Night**	X

Timesheet #	49012	**Employee #**	357951

Critical Devices – Life Saving Action

Safe [S] At Risk [R] Imminent Hazard [I] N/A [N]

		S	R	I	N
01	Is a Work Authorization Permit and/or Variance in place and at the work front to bypass/defeat a Safety Critical Device?	X			
02	Alternative controls in place to manage risks while Safety Critical Device is defeated?	X			
03	Is there an emergency response plan during safety critical device defeat?				X
04	Safety critical device defeat/bypass is documented?				X
05	Safety critical device defeat/bypass is communicated?		X		
06	Have crane computer by-passes/alarms been tampered with or disabled?			X	
07	Tools equipped with built-in safety features? (spring loaded safety knives, deadman switches, etc.) And safety features not bypassed	X			
08	Are tools with triggers being used properly? The trigger is not locked down	X			
09	Are tools with guards and handles being used properly			X	

CCZJV Expectation Questions	**Yes**	**No**	**N/A**
Has positive feedback provided?		X	
Has the job been stopped in the event of an imminent hazard?		X	
Has an investigation been conducted?	X		
Have corrective actions been taken?		X	

Comments:

Great teamwork and performance.

FAILED TEST FORM