NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-1C5D124BBD
Inspection time (UTC)	2026-10-22T13:24:27.335810+00:00
Input filename	demo_wafer_0036.npy
Model	MobileNetV2 V2
Predicted class	Loc
Confidence	91.91%
Inspection status	HIGH CONFIDENCE PREDICTION
Total die pixels	5592
Defective die pixels	0
Defect ratio	0.00%
Provisional severity	LOW

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	0.03%
Donut	0.38%
Edge-Loc	3.40%
Edge-Ring	1.35%
Loc	91.91%
Near-full	0.17%
Random	0.30%
Scratch	0.78%
none	1.68%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.