NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-2311FDB773
Inspection time (UTC)	2026-10-22T13:24:26.568737+00:00
Input filename	demo_wafer_0031.npy
Model	MobileNetV2 V2
Predicted class	Scratch
Confidence	47.00%
Inspection status	MANUAL REVIEW
Total die pixels	5592
Defective die pixels	1956
Defect ratio	34.98%
Provisional severity	HIGH

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	0.02%
Donut	0.06%
Edge-Loc	32.23%
Edge-Ring	19.60%
Loc	0.25%
Near-full	0.30%
Random	0.16%
Scratch	47.00%
none	0.38%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.