NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-66EEE8B156
Inspection time (UTC)	2026-10-22T13:24:31.139819+00:00
Input filename	demo_wafer_0061.npy
Model	MobileNetV2 V2
Predicted class	Scratch
Confidence	66.91%
Inspection status	MANUAL REVIEW
Total die pixels	5592
Defective die pixels	218
Defect ratio	3.90%
Provisional severity	MODERATE

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	2.81%
Donut	0.24%
Edge-Loc	6.67%
Edge-Ring	1.77%
Loc	7.46%
Near-full	0.06%
Random	0.69%
Scratch	66.91%
none	13.38%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.