# NANO SENTINEL

## Wafer Inspection Report

| | |
|---|---|
| Inspection ID | NS-70D16629FC |
| Inspection time (UTC) | 2026-10-22T13:24:25.887235+00:00 |
| Input filename | demo_wafer_0027.npy |
| Model | MobileNetV2 V2 |
| Predicted class | Loc |
| Confidence | 91.91% |
| Inspection status | HIGH CONFIDENCE PREDICTION |
| Total die pixels | 5592 |
| Defective die pixels | 0 |
| Defect ratio | 0.00% |
| Provisional severity | LOW |

### *Inspection recommendation*

Review the wafer map and model output before taking corrective action.

### *Class probabilities*

| Class | Probability (%) |
|---|---|
| Center | 0.03% |
| Donut | 0.38% |
| Edge-Loc | 3.40% |
| Edge-Ring | 1.35% |
| Loc | 91.91% |
| Near-full | 0.17% |
| Random | 0.30% |
| Scratch | 0.78% |
| none | 1.68% |

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.