NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-8DF19F97F5
Inspection time (UTC)	2026-10-22T13:24:24.024599+00:00
Input filename	demo_wafer_0014.npy
Model	MobileNetV2 V2
Predicted class	Loc
Confidence	54.06%
Inspection status	MANUAL REVIEW
Total die pixels	5592
Defective die pixels	137
Defect ratio	2.45%
Provisional severity	MODERATE

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	24.46%
Donut	21.17%
Edge-Loc	0.00%
Edge-Ring	0.00%
Loc	54.06%
Near-full	0.00%
Random	0.00%
Scratch	0.19%
none	0.11%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.