NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-B7BE1F13D5
Inspection time (UTC)	2026-10-22T13:24:29.173597+00:00
Input filename	demo_wafer_0048.npy
Model	MobileNetV2 V2
Predicted class	Loc
Confidence	77.22%
Inspection status	REVIEW RECOMMENDED
Total die pixels	5592
Defective die pixels	421
Defect ratio	7.53%
Provisional severity	HIGH

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	0.05%
Donut	0.07%
Edge-Loc	1.42%
Edge-Ring	0.04%
Loc	77.22%
Near-full	0.01%
Random	0.05%
Scratch	18.81%
none	2.32%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.