NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-C6FA87409C
Inspection time (UTC)	2026-10-22T13:24:33.846718+00:00
Input filename	demo_wafer_0079.npy
Model	MobileNetV2 V2
Predicted class	Scratch
Confidence	42.66%
Inspection status	MANUAL REVIEW
Total die pixels	5592
Defective die pixels	389
Defect ratio	6.96%
Provisional severity	HIGH

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	0.24%
Donut	2.81%
Edge-Loc	20.15%
Edge-Ring	19.54%
Loc	2.92%
Near-full	0.10%
Random	4.21%
Scratch	42.66%
none	7.37%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.