NANO SENTINEL

Wafer Inspection Report

Inspection ID	NS-CAFD3B06C1
Inspection time (UTC)	2026-10-22T13:24:30.070829+00:00
Input filename	demo_wafer_0055.npy
Model	MobileNetV2 V2
Predicted class	Center
Confidence	44.79%
Inspection status	MANUAL REVIEW
Total die pixels	5592
Defective die pixels	656
Defect ratio	11.73%
Provisional severity	HIGH

Inspection recommendation

Review the wafer map and model output before taking corrective action.

Class probabilities

Class	Probability (%)
Center	44.79%
Donut	41.27%
Edge-Loc	0.00%
Edge-Ring	0.00%
Loc	13.73%
Near-full	0.00%
Random	0.01%
Scratch	0.00%
none	0.19%

Important: model confidence does not guarantee correctness. Defect ratio and severity are provisional pixel-map heuristics, not validated manufacturing standards. A qualified engineer should review the wafer map before taking corrective action.