



PRE-DISPATCH INSPECTION REPORT (PDIR)

SHIPMENT & PART INFORMATION

SUPPLIER / ORGANIZATION

SHIPMENT NUMBER (DESSIMATE TO PROVIDE)
FH26-001

PART DESCRIPTION
Flanged Head

SALES ORDER NO.

INSPECTION DATE
03/03/26

COUNTRY OF ORIGIN
India

MODE OF SHIPMENT
Air Shipment

PART NUMBER
007157-001

PO NUMBER
3004

QTY INSPECTED
290

INSPECTOR
Dhiraj Patil

DESTINATION COUNTRY
USA

INVOICE / AWB NO.
GMTCX25261264

INSPECTION CHECKLIST

Inspection Item	Pass	Fail	Comments
Dimensions per drawing	☒	☐	
Material verified	☒	☐	
Surface finish	☒	☐	
Color / appearance	☒	☐	
Assembly complete	☐	☐	N/A
Labeling correct	☒	☐	
Packaging correct	☒	☐	
Quantity verified	☒	☐	
Documentation included	☒	☐	
Final visual inspection	☒	☐	

SUPPORTING DOCUMENTS

The following supplier documents were submitted with this shipment and are attached to this PDF as file attachments (visible in a PDF reader's attachments/paperclip panel).

Supplier CTQ Dimensional Inspection Report: PDIR_Flanged Head_007157-001.pdf

Supplier Invoice: Inv no.1264.pdf

Supplier MTC Report: MTC_Flanged Head_007157-001.pdf



PRE-DISPATCH INSPECTION REPORT (PDIR)

PART PICTURES (MINIMUM 3 PHOTOS PER PART)

	Photo 2	Photo 3
Photo 4	Photo 5	Photo 6
Photo 7	Photo 8	Photo 9

NON-CONFORMANCE / REMARKS

DISPOSITION

☒ Approved for Shipment

☐ Rework Required

☐ Hold for Review

SIGN-OFF

PREPARED BY (SIGNATURE)

Roberto Marin

QUALITY APPROVAL (SIGNATURE)

Roberto Marin

DATE

03/03/26

PRINT NAME

Roberto Marin

PRINT NAME

Roberto Marin

TITLE

Director