



PRE-DISPATCH INSPECTION REPORT (PDIR)

SHIPMENT & PART INFORMATION

SHIPMENT NUMBER (DESSIMATE TO PROVIDE)

FH26-001

PART NUMBER

007157-001

PART DESCRIPTION

Flanged Head

PO NUMBER

3004

SALES ORDER NO.

QTY INSPECTED

290

INSPECTION DATE

03/0/326

INSPECTOR

Dhiraj Patil

COUNTRY OF ORIGIN

India

DESTINATION COUNTRY

USA

MODE OF SHIPMENT

Air Shipment

INVOICE / AWB NO.

GMTCX25261264

INSPECTION CHECKLIST

Inspection Item	Pass	Fail	Comments
Dimensions per drawing	☒	☐	
Material verified	☒	☐	
Surface finish	☒	☐	
Color / appearance	☒	☐	
Assembly complete	☐	☐	N/A
Labeling correct	☒	☐	
Packaging correct	☒	☐	
Quantity verified	☒	☐	
Documentation included	☒	☐	
Final visual inspection	☒	☐	

SUPPORTING DOCUMENTS

The following supplier documents were submitted with this shipment and are attached to this PDF as file attachments (visible in a PDF reader's attachments/paperclip panel).

Supplier CTQ Dimensional Inspection Report: PDIR_Flanged Head_007157-001.pdf

Supplier Invoice: Invoice no. GMTCX25261264 Dessimate Flanged Head 290 Nos.jpeg

Supplier MTC Report: MTC_Flanged Head_007157-001.pdf



PRE-DISPATCH INSPECTION REPORT (PDIR)

PART PICTURES (MINIMUM 3 PHOTOS PER PART)

Photo 1	Photo 2	Photo 3
Photo 4	Photo 5	Photo 6
Photo 7	Photo 8	Photo 9

NON-CONFORMANCE / REMARKS

DISPOSITION

☐ Approved for Shipment

☐ Rework Required

☐ Hold for Review

SIGN-OFF

PREPARED BY (SIGNATURE)

Roberto Marin

QUALITY APPROVAL (SIGNATURE)

Roberto Marin

DATE

03/03/26

PRINT NAME

Roberto Marin

PRINT NAME

Roberto Marin

TITLE

Director