



PRE-DISPATCH INSPECTION REPORT (PDIR)

SHIPMENT & PART INFORMATION

SHIPMENT NUMBER (DESSIMATE TO PROVIDE)

FH26-10

PART NUMBER

007156-001

PART DESCRIPTION

Flanged Head

PO NUMBER

3004

SALES ORDER NO.

N/A

QTY INSPECTED

640

INSPECTION DATE

08/18/26

INSPECTOR

RM

COUNTRY OF ORIGIN

India

DESTINATION COUNTRY

USA

MODE OF SHIPMENT

Sea-Cargo

INVOICE / AWB NO.

8-16-2026 GMTC 2627 0628

INSPECTION CHECKLIST

Inspection Item	Pass	Fail	Comments
Dimensions per drawing	☒	☐	
Material verified	☒	☐	
Surface finish	☒	☐	
Color / appearance	☒	☐	
Assembly complete	☐	☐	N/A
Labeling correct	☒	☐	
Packaging correct	☒	☐	
Quantity verified	☒	☐	
Documentation included	☒	☐	
Final visual inspection	☒	☐	

CTQ DIMENSIONAL MEASUREMENTS - 3 PIECES SAMPLED

Record all critical-to-quality dimensions called out on the drawing. Measure 3 pieces per lot; mark each dimension Pass or Fail against tolerance.

Balloon #	CTQ Dimension / Feature	Nominal	Tolerance ($\pm$)	Pc 1	Pc 2	Pc 3	Result



PRE-DISPATCH INSPECTION REPORT (PDIR)

PART PICTURES (MINIMUM 3 PHOTOS PER PART)

Photo 1	Photo 2	Photo 3
Photo 4	Photo 5	Photo 6
Photo 7	Photo 8	Photo 9

NON-CONFORMANCE / REMARKS

DISPOSITION

☒ Approved for Shipment

☐ Rework Required

☐ Hold for Review

SIGN-OFF

PREPARED BY (SIGNATURE)

VK

QUALITY APPROVAL (SIGNATURE)

VK

DATE

08/18/26

PRINT NAME

VK

PRINT NAME

VK

TITLE