



PRE-DISPATCH INSPECTION REPORT (PDIR)

SHIPMENT & PART INFORMATION

SUPPLIER / ORGANIZATION

GMT

SHIPMENT NUMBER (DESSIMATE TO PROVIDE)

FH26-005

PART DESCRIPTION

Flanged Head

SALES ORDER NO.

INSPECTION DATE

06/18/25

COUNTRY OF ORIGIN

India

MODE OF SHIPMENT

Ocean

PART NUMBER

007157-001

PO NUMBER

3004

QTY INSPECTED

Dhiraj Patil

INSPECTOR

300

DESTINATION COUNTRY

US

INVOICE / AWB NO.

GMTCX/2627/0286

INSPECTION CHECKLIST

Inspection Item	Pass	Fail	Comments
Dimensions per drawing	☒	☐	
Material verified	☒	☐	
Surface finish	☒	☐	
Color / appearance	☒	☐	
Assembly complete	☐	☐	NA
Labeling correct	☒	☐	
Packaging correct	☒	☐	
Quantity verified	☒	☐	
Documentation included	☒	☐	
Final visual inspection	☒	☐	

SUPPORTING DOCUMENTS

The following supplier documents were submitted with this shipment and are attached to this PDF as file attachments (visible in a PDF reader's attachments/paperclip panel).

Supplier CTQ Dimensional Inspection Report: PDIR - Dispatch Documents - Invoice No 0286.pdf

Supplier Invoice: exp inv-286 (1).pdf

Supplier MTC Report: Foundry MTC.pdf



PRE-DISPATCH INSPECTION REPORT (PDIR)

PART PICTURES (MINIMUM 3 PHOTOS PER PART)



Photo 3

Photo 4

Photo 5

Photo 6

Photo 7

Photo 8

Photo 9

NON-CONFORMANCE / REMARKS

DISPOSITION

☒ Approved for Shipment

☐ Rework Required

☐ Hold for Review

SIGN-OFF

PREPARED BY (SIGNATURE)

Roberto Marin

QUALITY APPROVAL (SIGNATURE)

Roberto Marin

DATE

05/15/26

PRINT NAME

Roberto Marin

PRINT NAME

Roberto Marin

TITLE

Director