

VISIONGUARD EDGE

AI-POWERED MSME QUALITY INSPECTION REPORT (OFFLINE PROTO)

Inspection ID	42	Date/Time	2026-08-20 12:00:00
Product ID	PCB-042	Model Version	YOLOv8n-PCB-v1.0

■ DEFECT DETECTED (FAIL)

Visual Classification Check	Component Misalignment
AI Inference Confidence	94.6%

Inspection Visual Record

Visual image capture reference was not archived or is unavailable.

Industrial Quality Recommendations

- ■ Adjust conveyor guide rails or recalibrate camera spatial alignment coordinates.
- Perform hot-air rework on the component to realign pad positions.

Notice: This report is generated automatically by VisionGuard Edge AI Prototype engine for hackathon review. It is intended to serve as a design framework for industrial IoT quality systems.