Service report

Synthetic sample V10. Fill in one report per visit and keep a copy with the job file.

Job no.	J-30417
Site	Pumping station 7, Lowmoor
Description	Pump service and replacement of the shaft seal
Hours	3.5
Engineer	B. Castellanos