# Site inspection memo (SYNTHETIC)

The inspection covered the north and south loading docks on 14 May.
Calibration records for the forklift scales were complete and current.
Two fire doors were found wedged open during the morning shift.
Staff training logs were signed by the shift supervisor in all cases.
Pallet racking inspections are due again within ninety days.
The drainage channel beside dock B was clear of debris and oil.