RePET Inc.™
Local Recycling. Global Impact.

Production Report

DATE
2026-11-02

SHIFT
1 | **2** | 3

LINE
1 | 2 | 3

SUPERVISOR
Josue Medina

SAFETY TARGET
ZERO INJURIES

QUALITY TARGET
NO ALUMINUM / NO PVC

PRODUCTION TARGET
L1: 2 MT/HR
L2: 5 MT/HR
L3: 5 MT/HR

DAILY BALE INPUT TARGET

Shift	Monday	Tuesday	Wednesday	Thursday	Friday
S1	137	120	137	91	137
S2	137	85	137	108	137
S3	137	131	137	137	125

NUMBER OF EMPLOYEES
12

INJURIES / FIRST AID
Yes | No

LINE START TIME
09:33

TOTAL DOWNTIME
1 **hrs** 0 **min**

LINE STOP TIME
09:33

TOTAL RUN TIME
8 **hrs** 0 **min**

Input Data

TOTAL INPUT BALES
123

TOTAL INPUT BALE WEIGHT
123,412 LBS

TOTAL REPROCESSED MATERIALS
2,583 LBS

Rewash Bags Information (Optional)

REWASH WEIGHT TOTAL 2,583 LBS

+ Add Bag

BAG DATE	SHIFT	LINE	BAG TYPE	BAG NUMBER	BAG WEIGHT (LBS)
2026-11-02	2	1	Color	1	1341
2026-11-02	2	1	Label	2	1242

Output Data

TOTAL OUTPUT PET FLAKE BAGS: 40

TOTAL OUTPUT FLAKE WEIGHT (LBS): 92,299

OUTPUT PET FINES BAGS WEIGHTS (LBS): 1,233

OUTPUT PET FINES BAGS: 21

OUTPUT METRIC TONS (2204LBS/MT): 40.71 MT

Automatically calculated: (Total Output Flake Weight (LBS) - Total Reprocessed Materials (LBS)) / 2204

Baler Machine Data

BALER MACHINE PRODUCED BALES: 12

INPUT BALE RATIO: 12

BALER MACHINE START TIME: 09:46

BALER MACHINE STOP TIME: 02:46

Blade Change Information

BLADE CHANGE TOTAL 60 MIN

+ Add Input

GRINDER	START TIME	END TIME
No.1	09:46	10:46

Total: **60** min

Purple Pipe and Wastewater Usage

	TIME	METER READING	USAGE	Log	GPM	Usage/8/60
Purple pipe	09:46	5853586.66	11691 (meter − prior) × 7.48		24.36	

	TIME	DISCHARGE	USAGE	Log	GPM	Usage/8/60
Wastewater	09:47	9982572	11231 (discharge − prior) × 7.48		23.40	

OPEN BALER CLEANLINESS

3/3 checked

EQUIPMENT	CONDITION	OPERATOR CLEANED	PHOTOS
Auger #1	Clean / Dirty	Yes / No	Add photo
	1/3 photos		
Open photo: openBalerCle...			
Auger #2	Clean / Dirty	Yes / No	Add photo
Auger #3	Clean / Dirty	Yes / No	Add photo
	1/3 photos		
Open photo: openBalerCle...			

TWIN AUGER CLEANLINESS

5/5 checked

EQUIPMENT	CONDITION	OPERATOR CLEANED	PHOTOS
Twin Auger #1	Clean / Dirty	Yes / No	Add photo
Twin Auger #2	Clean / Dirty	Yes / No	Add photo
Twin Auger #3	Clean / Dirty	Yes / No	Add photo
	1/3 photos		
Open photo: twinAugerCle...			
Twin Auger #4	Clean / Dirty	Yes / No	Add photo
	1/3 photos		
Open photo: twinAugerCle...			

Twin Auger #5	Clean	Dirty	Yes	No	Add photo

DOWNTIME ITEMS/PRODUCTION NOTES

test

COMPLETED BY (PRINT FULL NAME)

Daniela Villegas

DATE SUBMITTED

2026-11-02

SUPERVISOR REVIEW (SIGNATURE OR INITIALS)

DV

Submitting Report