

Ref: FLT-1008
Date: 2026-08-25
Plant: C3
Severity: Medium
Raised by: Dexter Norley
Stage: Reported

Description

Drain leaking water, drain line heater is working as per attached picture.

Action taken / recommendation

Recommend all drains to be replaced with a greater fall and the removal of the hepvo trap.

Photo 1

