

Ref: WK-MU5V1C28
 Date: 2026-09-17
 Engineer: Dexter Norley
 Plant: A & B, C & D, E
 Week: 38
 Ambient °C: 17.7
 Faults recorded: 0

Faults recorded on this visit

None - no line item was flagged.

A & B - Chamber temperature

Item	A1	A2	A3	A4	No1 B2	No2 B2	No3 B1	No4 B1
Cold store set point (controller)	-20	-20	-20	-20	-18.9	-18	-18.9	-18.2
Cold store temp air-on	-17.4	-17.6	-18.4	-18.3	-16.5	-16.3	-16.9	-16.2
Coolers air off	-19.7	-19.8	-19.9	-20.8	-19.8	-17.9	-18.1	-18
Cooling on/off	On	On	On	On	On	On	On	On

A & B - Coolers

Item	A1	A2	A3	A4	No1 B2	No2 B2	No3 B1	No4 B1
Cooler fan correct operation	OK	OK	OK	OK	OK	OK	OK	OK
Cooler correct operation	OK	OK	OK	OK	OK	OK	OK	OK
Cooler correct defrosting cycle	OK	OK	OK	OK	OK	OK	OK	OK
Cooler ice build-up & debris	OK	OK	OK	OK	OK	OK	OK	OK
Defrost drain line for leakage	OK	OK	OK	OK	OK	OK	OK	OK
Operating suction superheat #	8.2	4	7.4	6.7	8.8	6	6	5.3
% opening of expansion valve #	49	44	20	46	100	12	13	39
Cooler air temp diff #	2.3	2.2	1.5	2.5	3.3	1.6	1.2	1.8

A & B - Compressor racks & condenser

Item	A	B
Compr abnormal noise / vibration	OK	OK
Oil cooler fin face free of debris	OK	OK
Oil cooler fans correct operation	OK	OK
Plant-room ventilation fan (on/off)	On	On
Plant-room temperature	30.2	30.2
Wet-matt cooling on/off (hours)	On	Off
System delivery pressure	14.6	14.8
Condenser fin face free of debris	OK	OK
Condenser fans correct operation	No	Yes
Liquid line sight glass	Clear	Clear
Receiver level	Above bottom sight glass	Below bottom sight glass
Oil separator oil level	Full	Full
No1 compressor running & % load	100	0
No2 compressor running & % load	0	100

Item	A	B
No3 compressor running & % load	0	-
No1 compr delivery & econ temp	Delivery 63 econ 7	Off
No2 compr delivery & econ temp	Not running	Delivery 69 econ 25
No3 compr delivery & econ temp	Not running	-
Refrigerant leak detection system	OK	OK

A & B - Controls

Item	A	B
Suction pressure	0.7	0.9
Suction temperature	-12.6	-17
Suction SH	16	8
Delivery pressure	14.1	14.8
Common delivery temp	63.4	69.9
Oil temperature	46.6	45.2
HP liquid temperature	26	32
HP liquid sub-cooling	9	4
Econ liquid temperature	16.5	13.7
Econ sub-cooling	19	22

A & B - Main incoming meter

Item	kWhr
Electric kWhr meter reading	685540
Previous meter reading	679383
Total kWhr	6157

A & B - A - pack meter

Item	kWhr
Electric kWhr meter reading	4616392
Previous meter reading	4603708
Pack total kWhr	12684
A chamber total energy	17061

A & B - B - pack meter

Item	kWhr
Electric kWhr meter reading	2843722
Previous meter reading	2831039
Pack total kWhr	12683
B chamber total energy	16,843

A & B - A & B cooler energy meter

Item	kWhr
Electric kWhr meter reading	2626615
Previous meter reading	2618078
Total kWhr	8537

A & B - B cooler energy meter

Item	kWhr
Electric kWhr meter reading	702713
Previous meter reading	698553
Total kWhr	4160

A & B - A cooler energy (derived)

Item	kWhr
Electric kWhr meter reading	1923902
Previous meter reading	1919525
Total kWhr	4377

C & D - Chamber temperature

Item	C1	C2	C3	C4	D1	D2
Cold store set point (controller)	-18	-18.8	-18.2	-18.2	-18.6	-18.1
Cold store temp air-on	-17.5	-18.1	-18.5	-18.6	-18.5	-18.3
Coolers air off	-21.9	-19.2	-18.6	-18.6	-20.5	-18.3
Cooling on/off	On	On	Off	Off	On	Off

C & D - Condensing units

Item	C1	C2	C3	C4	D1	D2	D3	D4
Compr abnormal noise / vibration	OK	OK	OK	OK	OK	OK	OK	OK
Compressor abnormal frosting	OK	OK	OK	OK	OK	OK	OK	OK
Compr oil level	2/3	2/3	2/3	2/3	2/3	2/3	2/3	2/3
Compr delivery temperature	65	64	67	63	68	67	67	67
Oil recovery / separator level	Full	Full	Full	Full	Full	Full	Full	Full
Condenser fin face free of debris	OK	OK	OK	OK	OK	OK	OK	OK
Condenser fans abnormal noise	OK	OK	OK	OK	OK	OK	OK	OK
Liquid line sight glass	OK	OK	OK	OK	OK	OK	OK	OK
Receiver level	Below sight glass	Above sight glass	Below sight glass	Above bottom sight glass	Below bottom sight glass	Below bottom sight glass	Below bottomsight glass	Below bottom sight glass

C & D - Coolers

Item	C1	C2	C3	C4	D1	D2
Cooler temperature diff	2.4	1.1	0.1	0	2	0
Cooler correct operation	OK	OK	OK	OK	OK	OK
Cooler correct defrosting cycle	OK	OK	OK	OK	OK	OK
Cooler ice build-up & debris	OK	OK	OK	OK	OK	OK
Defrost drain line for leakage	OK	OK	OK	OK	OK	OK

C & D - Energy readings

Item	C2-4 refrig	C1-3 refrig	D 1&2	D 3&4 compr
Electric kWhr meter reading	3012717	1122007	2629933	24404
Previous kWhr meter reading	3007777	1117419	2621539	24351
Total kWhr	4940	4588	8395	53
Chamber total energy		9528		8448

E - Chamber temperature

Item	E1	E2
Cold store set point (controller)	-18.6	-18
Cold store temp air-on	-18.3	-18.4
Coolers air off	-19.2	-18.5
Cooling on/off	On	Off

E - E chamber front-centre temp

Item	°C
Front-centre temperature	-16.8

E - Condensing units

Item	E1 Compr1	E1 Compr2	E2 Compr1	E2 Compr2
Compr abnormal noise / vibration	OK	OK	OK	OK
Compressor abnormal frosting	OK	OK	OK	OK
Compr oil level	2/3	2/3	2/3	2/3
Compr delivery temperature	67	67	66	68
Oil recovery / separator level	Full	Full	Full	Full
Condenser fin face free of debris	OK	OK	OK	OK
Condenser fans abnormal noise	OK	OK	OK	OK
Liquid line sight glass	OK	OK	OK	OK
Receiver level	Above bottom sight glass	Above bottom sight glass	Below bottom sight glass	Below bottom sight glass

E - Coolers

Item	E1	E2
Cooler temperature diff	0.9	0.1
Cooler correct operation	OK	OK
Cooler correct defrosting cycle	OK	OK
Cooler ice build-up & debris	OK	OK
Defrost drain line for leakage	OK	OK

E - System readings

Item	E1	E2
Suction pressure	0.9	0.8
Suction temperature	-15	-16
Suction superheat	11	11
Delivery pressure	12.5	13
Liquid refrig temperature	26	27
Liquid sub	6	6

E - Energy readings

Item	E1	E2
Electric kWhr meter reading	14060	12617
Previous kWhr meter reading	13950	12585
Total kWhr	110	32
Chamber total energy		142

RDM alarms at time of visit

Item	Asset / chamber	Active since	Outcome	Action taken / reason
Stage 2 fault.	A plant.	2026-09-10	Ongoing	New fan quoted.