

Ref: WK-MUO0F33K
 Date: 2026-09-30
 Engineer: Dexter Norley
 Plant: A & B, C & D, E
 Week: 40
 Ambient °C: 17.9
 Faults recorded: 1

Faults recorded on this visit (1)

Ref	Asset	Location / item	Severity	Action taken
FLT-1026	A	A & B - Compressor racks & condenser - Condenser fans correct operation	High	Quote

Open faults reviewed on this visit (3)

Ref	Asset	Open (days)	Position	Evidence / reason
FLT-1005	A	37	STILL OPEN	Awaiting quotation - Quotes sent out
FLT-1011	A	35	STILL OPEN	Awaiting client approval - Quote sent
FLT-1012	A&B Plant Room	35	STILL OPEN	Awaiting access - Quote sent out

A & B - Chamber temperature

Item	A1	A2	A3	A4	No1 B2	No2 B2	No3 B1	No4 B1
Cold store set point (controller)	-20	-20	-20	-20	-18.9	-18.9	-18.9	18.9
Cold store temp air-on	-18	-18.1	-18.3	-17.8	-16.9	-17.2	-17.8	-18.5
Coolers air off	-19.4	-19.2	-21	-19.4	-20	-20.2	-20.4	-20.2
Cooling on/off	On	On	On	On	On	On	On	On

A & B - Coolers

Item	A1	A2	A3	A4	No1 B2	No2 B2	No3 B1	No4 B1
Cooler fan correct operation	OK	OK	OK	OK	OK	OK	OK	OK
Cooler correct operation	OK	OK	OK	OK	OK	OK	OK	OK
Cooler correct defrosting cycle	OK	OK	OK	OK	OK	OK	OK	OK
Cooler ice build-up & debris	OK	OK	OK	OK	OK	OK	OK	OK
Defrost drain line for leakage	OK	OK	OK	OK	OK	OK	OK	OK
Operating suction superheat #	7.2	8.3	8.8	8.2	4.6	7.2	6.8	9.4
% opening of expansion valve #	38	45	61	47	56	58	100	100
Cooler air temp diff #	1.4	1.1	2.7	1.6	3.1	3	2.6	1.7

A & B - Compressor racks & condenser

Item	A	B
Compr abnormal noise / vibration	OK	OK
Oil cooler fin face free of debris	OK	OK
Oil cooler fans correct operation	OK	OK
Plant-room ventilation fan (on/off)	On	On
Plant-room temperature	34.5	34.5
Wet-matt cooling on/off (hours)	On	Off
System delivery pressure	19bar	18bar
Condenser fin face free of debris	OK	OK

Item	A	B
Condenser fans correct operation	Fan 3 u/s	Yes
Condenser fans correct operation - flagged	FAULT	
Liquid line sight glass	Clear	Clear
Receiver level	Above bottom sight glass	Below bottom sight glass
Oil separator oil level	Fill	Full
No1 compressor running & % load	75%	75%
No2 compressor running & % load	100%	100%
No3 compressor running & % load	Off	-
No1 compr delivery & econ temp	Delivery 67c econ off	Delivery 76c econ off
No2 compr delivery & econ temp	Delivery 68c econ 3c	Delivery 68c econ 11c
No3 compr delivery & econ temp	Off	-
Refrigerant leak detection system	OK	OK

A & B - Controls

Item	A	B
Suction pressure	0.9 bar	0.5 bar
Suction temperature	-14.7c	-18.7
Suction SH	11c	12.3
Delivery pressure	19 bar	18bar
Common delivery temp	76.4c	82.6c
Oil temperature	48.1c	50.5
HP liquid temperature	37c	37c
HP liquid sub-cooling	8c	6c
Econ liquid temperature	9c	18c
Econ sub-cooling	36c	25c

A & B - Main incoming meter

Item	kWhr
Electric kWhr meter reading	695836
Previous meter reading	690352
Total kWhr	5483

A & B - A - pack meter

Item	kWhr
Electric kWhr meter reading	4637700
Previous meter reading	4626304
Pack total kWhr	11396
A chamber total energy	15452

A & B - B - pack meter

Item	kWhr
Electric kWhr meter reading	2865181
Previous meter reading	2854355
Pack total kWhr	10826
B chamber total energy	14775

A & B - A & B cooler energy meter

Item	kWhr
Electric kWhr meter reading	2641341
Previous meter reading	2633336
Total kWhr	8005

A & B - B cooler energy meter

Item	kWhr
Electric kWhr meter reading	710007.
Previous meter reading	706058
Total kWhr	3949

A & B - A cooler energy (derived)

Item	kWhr
Electric kWhr meter reading	1931334
Previous meter reading	1927278
Total kWhr	4056

C & D - Chamber temperature

Item	C1	C2	C3	C4	D1	D2
Cold store set point (controller)	-18.8	-18.8	-18.8	-18.8	-18.6	-18.1
Cold store temp air-on	-18.2	-18.8	-18.7	-19.3	-18.8	-18.8
Coolers air off	-22.2	-19.7	-19.8	-19.3	-21	-18.8
Cooling on/off	On	On	On	Off	On	Off

C & D - Condensing units

Item	C1	C2	C3	C4	D1	D2	D3	D4
Compr abnormal noise / vibration	OK	OK	OK	OK	OK	OK	OK	OK
Compressor abnormal frosting	OK	OK	OK	OK	OK	OK	OK	OK
Compr oil level	2/3	2/3	2/3	2/3	2/3	2/3	2/3	2/3
Compr delivery temperature	82	78	79	78	72	72	74	74
Oil recovery / separator level	Full	Full	Full	Full	Full	Full	Full	Full
Condenser fin face free of debris	OK	OK	OK	OK	OK	OK	OK	OK
Condenser fans abnormal noise	OK	OK	OK	OK	OK	OK	OK	OK
Liquid line sight glass	OK	OK	OK	OK	OK	OK	OK	OK
Receiver level	Below bottom sight glass	Above bottom sight glass	Below bottom sight glass	Above bottom sight glass	Below bottom sight glass	Below bottom sight glass	Below bottom sight glass	Below bottom sight glass

C & D - Coolers

Item	C1	C2	C3	C4	D1	D2
Cooler temperature diff	4c	0.9	1.1	0	2.2	0
Cooler correct operation	OK	OK	OK	OK	OK	OK
Cooler correct defrosting cycle	OK	OK	OK	OK	OK	OK
Cooler ice build-up & debris	OK	OK	OK	OK	OK	OK
Defrost drain line for leakage	OK	OK	OK	OK	OK	OK

C & D - Energy readings

Item	C2-4 refig	C1-3 refig	D 1&2	D 3&4 compr
Electric kWhr meter reading	3021777	1129210	2643710	24486
Previous kWhr meter reading	3016777	1125128	2636251	24442
Total kWhr	5000	4082	7459	44
Chamber total energy		9082		7503

*The work that **keeps you working.***

E - Chamber temperature

Item	E1	E2
Cold store set point (controller)	-18.6	-18.6
Cold store temp air-on	-18.7	-19
Coolers air off	-19.8	-20.1
Cooling on/off	On	On

E - E chamber front-centre temp

Item	°C
Front-centre temperature	-18

E - Condensing units

Item	E1 Compr1	E1 Compr2	E2 Compr1	E2 Compr2
Compr abnormal noise / vibration	OK	OK	OK	OK
Compressor abnormal frosting	OK	OK	OK	OK
Compr oil level	2/3	2/3	2/3	2/3
Compr delivery temperature	61	62	64	64
Oil recovery / separator level	Full	Full	Full	Full
Condenser fin face free of debris	OK	OK	OK	OK
Condenser fans abnormal noise	OK	OK	OK	OK
Liquid line sight glass	OK	OK	OK	OK
Receiver level	Above bottom sight glass	Above bottom sight glass	Below bottom sight glass	Below bottom sight glass

E - Coolers

Item	E1	E2
Cooler temperature diff	1.1	1.1
Cooler correct operation	OK	OK
Cooler correct defrosting cycle	OK	OK
Cooler ice build-up & debris	OK	OK
Defrost drain line for leakage	OK	OK

E - System readings

Item	E1	E2
Suction pressure	0.9	0.8
Suction temperature	-14	-15
Suction superheat	12c	12c
Delivery pressure	12.4	13
Liquid refrig temperature	28	28
Liquid sub	3c	5c

E - Energy readings

Item	E1	E2
Electric kWhr meter reading	14227	12669
Previous kWhr meter reading	14144	12634
Total kWhr	83	35
Chamber total energy		118

RDM alarms at time of visit

Item	Asset / chamber	Active since	Outcome	Action taken / reason
S02 stage fault 1	A chamber	2026-09-29	Ongoing	Quote for fan submitted