

Ref: FG-MT1BVLUI
Date: 2026-08-20
Engineer: Dexter Norley
Plant: C1, C2, C3, C4, D1, D2, E1, E2
Period: Jul–Dec 2026
As at: 2026-08-20
Contractor: Coolstream (UK) Ltd
F-Gas certification: Refcom company cert REF1018681 · valid to 08 Jul 2027
Detector: Fieldpiece Dr82 electronic leak detector (+ soapy water as needed)

C1 — C' system No1 (65kg R404a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

C2 — C' system No2 (75.5kg R404a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

C3 — C' system No3 (100kg R404a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

C4 — C' system No4 (100kg R404a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

D1 — D1' system No1 (82kg R404a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

D2 — D2' system No2 (75kg R449a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

E1 — E1' system No1 (60kg R449a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

E2 — E2' system No1 (60kg R449a)

Item	Result	Date	Comments
Electronic leak-detector test	No leak found	2026-08-20	
Indirect leak check	No loss indicated	2026-08-20	

