

Ref: 6M-MRBYPMD4
Date: 2026-07-08
Engineer: Dexter Norley
Plant: A, B, C, D, E
Period: Jul–Dec 2026
As at: 2026-07-08

Section A — condenser/oil-cooler wash

Item	Date washed	Comments
A section — air-cooled condenser	2026-07-08	Condenser in poor condition. Jet washed.

Section B — condenser/oil-cooler wash

Item	Date washed	Comments
B section — air-cooled condenser	2026-07-08	Condenser in poor condition. Jet washed.

Section C — condenser/oil-cooler wash

Item	Date washed	Comments
C1 — air-cooled condenser	2026-07-08	Showing signs of fin root.
C2 — air-cooled condenser	2026-07-08	Showing signs of fin root.
C3 — air-cooled condenser	2026-07-08	Showing signs of fin root.
C4 — air-cooled condenser	2026-07-08	Showing signs of fin root.

Section D — condenser/oil-cooler wash

Item	Date washed	Comments
D1 — air-cooled condenser	2026-07-08	Showing signs of fin root.
D2 — air-cooled condenser	2026-07-08	Showing signs of fin root.
D3 — air-cooled condenser	2026-07-08	Showing signs of fin root.
D4 — air-cooled condenser	2026-07-08	Showing signs of fin root.

Section E — condenser/oil-cooler wash

Item	Date washed	Comments
E1 — air-cooled condenser	2026-07-08	Showing signs of fin root.
E2 — air-cooled condenser	2026-07-08	Showing signs of fin root.