

Ref: WK-MQJ4RWKT
 Date: 2026-06-10
 Engineer: dex
 Plant: C & D, E
 Week: 1
 Issues flagged: 0

C & D — Chamber temperature

Item	C1	C2	C3	C4	D1	D2
Cold store set point (controller)	-18.3	-18	-18.8	-18	-18.6	-18.1
Cold store temp air-on	-17.9	-18	-18.9	-18.9	-18.5	-18.1
Coolers air off	-21.8	-19.8	-19	-19.3	-20.8	-20.8
Cooling on/off	-17.9/21.8	-18/19.8	-17/19	-18.8/18.5	-18/20.9	-20.8/18

C & D — Condensing units

Item	C1	C2	C3	C4	D1	D2	D3	D4
Compr abnormal noise / vibration	OK	OK	OK	OK	OK	OK	OK	OK
Compressor abnormal frosting	OK	OK	OK	OK	OK	OK	OK	OK
Compr oil level	Half	Full	2/3	Half	Full	Full	Full	Full
Compr delivery temperature	91	91	85	87	67	54	55	55
Oil recovery / separator level	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
Condenser fin face free of debris	OK	OK	OK	OK	OK	OK	OK	OK
Condenser fans abnormal noise	OK	OK	OK	OK	OK	OK	OK	OK
Liquid line sight glass	OK	OK	OK	OK	OK	OK	OK	OK
Receiver level	Below Half	Below Half	Below Half	Low	Full	Full	Full	Full

C & D — Coolers

Item	C1	C2	C3	C4	D1	D2
Cooler temperature diff	0.3	0.3	0.3	0.3	0.3	0.3
Cooler correct operation	OK	OK	OK	OK	OK	OK
Cooler correct defrosting cycle	OK	OK	OK	OK	OK	OK
Cooler ice build-up & debris	OK	OK	OK	OK	OK	OK
Defrost drain line for leakage	OK	OK	OK	OK	OK	OK

C & D — Energy readings

Item	C2-4 refrig	C1-3 refrig	D 1&2	D 3&4 compr
Electric kWhr meter reading	2938777	1057947	2523988	746844
Previous kWhr meter reading	2733177	1055947	2516795	745472
Total kWhr	5600	2000	7193	1372
Chamber total energy	7600	7600	8565	8565

E — Chamber temperature

Item	E1	E2
Cold store set point (controller)	-18.6	-18.1
Cold store temp air-on	18.3	-18
Coolers air off	-19	-17.8
Cooling on/off	-18.3/19.5	-16.9/17.8

E — Condensing units

Item	E1 Compr1	E1 Compr2	E2 Compr1	E2 Compr2
Compr abnormal noise / vibration	OK	OK	OK	OK
Compressor abnormal frosting	OK	OK	OK	OK
Compr oil level	2/3	2/3	Full	Full
Compr delivery temperature	67	64	65	68
Oil recovery / separator level	Full	Full	Full	Full
Condenser fin face free of debris	OK		OK	
Condenser fans abnormal noise	OK		OK	
Liquid line sight glass	OK		OK	
Receiver level	Low		Half	

E — Coolers

Item	E1	E2
Cooler temperature diff	0.3	0.3
Cooler correct operation	OK	OK
Cooler correct defrosting cycle	OK	OK
Cooler ice build-up & debris	OK	OK
Defrost drain line for leakage	OK	OK

E — System readings

Item	E1	E2
Suction pressure	0.6	0.6
Suction temperature	-18	-11
Suction superheat	10	14
Delivery pressure	12.4	13.8
Liquid refrig temperature	26	26
Liquid sub	9	12

E — Energy readings

Item	E1	E2
Electric kWhr meter reading	403563	391106
Previous kWhr meter reading	400282	391004
Total kWhr	3281	1102
Chamber total energy	4383	4383