

Inspection Form

Top Notch Chimney
1925 Park Avenue
Des Moines, IA 50315
Phone: (515) 249-6337
11/28/2020



Mr. Johnson
20 Applewood Dr

Height:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Chimney Cap / Spark Arrestor:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Crown / Wash:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Brickwork / Mortar:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Flashing:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Flue Liner:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Moisture Resistance:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Smoke Chamber:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Damper:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Firebox / Grate:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Ash Container:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Spark Screen / Doors:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Tools / Gloves:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Hearth Protection:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Miscellaneous:			
Bird screen put in place			
Stovepipe Condition (woodstove):	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
NFPA Approved Flue Connection:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Installation / Thimble / Clearances:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Fire Ext./ Smoke Detectors / CO Alarms:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Gas/Oil Furnace Flue Liner:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable
Fire Escape Plan:	<input checked="" type="radio"/> Satisfactory	<input type="radio"/> Unsatisfactory	<input type="radio"/> Not Applicable

TERMS

This inspection reports our observations of the inspected areas. In cases where we report "Unsatisfactory" these represent either a measured deviance from Code or NFPA recommendations, or our opinion is that some deviation exists. Where/if we report "Satisfactory", we cannot and do not warrant the inspected feature.
Caveat emptor.

Generate PDF