
PROJECT PORTFOLIO

REHABILITATION OF OLD OTUKPA - ORUKAM ROAD

Ogbadibo L.G.A., Benue State, Nigeria



Actual site photograph | Finished asphalt surface | 04 September 2026



TERTINDI REGINALD IGBAYUE

Construction Project Manager

Project delivery • Site coordination
Road rehabilitation • Drainage improvement

PROJECT DELIVERY ARRANGEMENT

Main contractor: Emma Ventures Investment Limited
Subcontractor: Boldhorizon | Works documented in August-September 2026


PROJECT OVERVIEW

Scope and delivery narrative

Rehabilitation works documented along the Old Otukpa-Orukam Road corridor, including drainage desilting, pothole excavation and asphalt surfacing.
The site records capture successive stages of execution and field coordination.



Project signboard / site context



Pothole excavation / preparation

Project management emphasis

- Sequencing of enabling works, drainage clearance and pavement preparation
- Coordination of labour, materials, plant and work-front access
- Traffic-interface awareness and site photographic documentation
- Inspection of work stages prior to subsequent operations

DOCUMENTARY NOTE

Photographs are original site records. GPS stamps are retained where present.
Dimensions, test results and completion certification are not asserted here.

PROJECT LEADERSHIP | DELIVERY RESPONSIBILITIES

REGINALD IGBAYUE · PROJECT MANAGER · BOLD HORIZON CONSTRUCTION

PROJECT INITIATION AND CLOSE-OUT

Led mobilisation, site takeover, operational execution and demobilisation for the approximately 1 km rehabilitation work package.

CONSTRUCTION PLANNING AND WORK-FRONT COORDINATION

Coordinated drainage interventions, failed-pavement excavation, pavement layer preparation and asphalt surfacing, aligning labour, engineers, operators and plant availability.

PROCUREMENT AND RESOURCE MANAGEMENT

Personally coordinated reinforcement steel, cement, water, formwork materials, lateritic fill and pavement inputs; arranged low-bed transport, grader, roller and equipment mobilisation.

DRAINAGE REHABILITATION AND FLOOD MITIGATION

Coordinated desilting of obstructed drains, sediment removal and repair of defective sections to restore conveyance and address reported surface-water flooding.

PROJECT MANAGEMENT | FIELD EXECUTION

REGINALD IGBAYUE · PROJECT MANAGER · BOLD HORIZON CONSTRUCTION

PAVEMENT REHABILITATION AND ASPHALT OPERATIONS

Managed site coordination for excavation of distressed sections, placement and compaction of stone-base materials, asphalt patching and overlay, delivery sequencing and work-front readiness.

WORKFORCE, PLANT AND SITE LOGISTICS

Organised local labour, engineering personnel and machine operators, together with wages, transport, accommodation, welfare and operational supplies.

STAKEHOLDER AND COMMUNITY ENGAGEMENT

Engaged community leaders, youth representatives and local stakeholders to coordinate access, local labour participation and construction interfaces.

PROJECT CONTROLS AND DOCUMENTATION

Coordinated site activity reporting, materials and delivery documentation, resource tracking and operational close-out. Formal engineering inspection and acceptance are separate approval processes.


DRAINAGE DESILTING & FLOOD MITIGATION

Restoring drainage conveyance


Existing drainage channels were reportedly obstructed by accumulated silt and debris, contributing to localised flooding. Desilting works aimed to reinstate a clearer flow path and reduce obstruction within the drainage network.



Drainage channel and accumulated sediment



Culvert passage after desilting activity



Additional drainage channel inspection




Open channel cleared of deposits

POTHOLE EXCAVATION & ROAD PREPARATION

Preparation of failed pavement sections


Distressed sections were opened and excavated to prepare the road for remedial works. The site photographs show exposed excavation areas and labour activity. Layer thicknesses and compaction acceptance require supporting site records.




Excavated potholes prior to reinstatement



Linear excavation / affected road section



Site crew engaged in surface preparation



Earthworks and manual excavation

ASPHALT WORKS & FIELD DOCUMENTATION

Surfacing operations

Original GPS-stamped photographs show asphalt surfacing in progress and the developing paved carriageway. Images are presented as field evidence, not as proof of specified density, material compliance or final acceptance.



Surfacing activity, 03 September 2026



New asphalt lane, same work period

Plant, tools and site logistics

Reported deployed resources: low-bed transport, hand compactor, spades, digger/excavator and water tanker. Specific plant photographs and equipment registers can be appended to substantiate individual deployments.


Professional delivery record

Key work packages: drainage desilting, flood mitigation, excavation, pavement preparation, asphalt surfacing and site coordination.
Client-facing issue: documentary portfolio; not an as-built or QA/QC certificate.


FINISHED ASPHALT SURFACE | SITE RECORD

Documented paved carriageway | 04 September 2026


Original GPS-stamped field photographs. Natural appearance retained.



01 Finished asphalt carriageway - wider road corridor view



02 Completed surfacing - oblique perspective




03 Road surface and adjacent road users


SURFACE FINISH | ADDITIONAL EVIDENCE

Post-surfacing photographic documentation


Recorded on 04 September 2026; images are not laboratory test evidence.



04 Continuous asphalt finish - longitudinal view




05 Finished pavement in service environment



06 Surface finish and pavement edge detail

ASPHALT DELIVERY | TRACEABILITY

MATERIAL RECEIPT / PRIMARY RECORD



WEIGHBRIDGE TICKET 1012

SUPPLIER	U U Cheson Investment Co. Ltd
CUSTOMER	BOLD HORIZON
MATERIAL	Asphalt
VEHICLE	DBR 13 XC
GROSS / TARE	44.55 t / 14.55 t
NET DELIVERED LOAD	**30.00 tonnes**

Evidence note: This is one documented weighbridge transaction. It does not establish total asphalt supplied, placed, or certified for the project.

SCOPE | TECHNICAL WORK PACKAGES

UNPRICED BOQ EXTRACT / PLANNED QUANTITIES

Site clearance / topsoil removal	**1,600 m2**
Concrete-lined drain repairs	**25 linear m**
Drainage desilting and cleaning	**200 linear m**
Lateritic sub-base, up to 150 mm compacted	**320 m3**
Lateritic base, up to 150 mm compacted	**320 m2***
Prime coat (MC0 / MC1 cutback)	**320 m2**
Asphalt concrete wearing course, 40 mm	**1,600 m2**

*The source BOQ lists the lateritic base unit as m2; its description also specifies a layer thickness. The measurement basis should be checked against approved contract documents.

Scope quantities are drawn from the priced BOQ supplied by the project team. Rates, amounts, subtotals and commercial values have been intentionally omitted. Quantities are not presented as measured or certified completion.

PROJECT MANAGEMENT | DELIVERY RECORD

SITE DIARY / 21 AUGUST - 02 SEPTEMBER 2026

21-22 AUG	Mobilisation, accommodation, community engagement, labour and site setup.
23-24 AUG	Drainage desilting, ground preparation, signboard and engineering logistics.
25-28 AUG	Material coordination, lateritic earthworks, excavation, masonry support and spoil removal.
29 AUG-02 SEP	Engineering mobilisation, drainage maintenance, equipment support and transport logistics.

DELIVERY CONTROL THEMES

- Stakeholder interface: local community leaders, youth representatives and road users.

- Resource planning: labour, construction materials, tools, plant movement and accommodation.

- Site operations: desilting, excavation, preparation, spoil removal and pavement work fronts.

- Document control: dated site diary, GPS photographs and asphalt delivery receipt.

EVIDENCE & ATTRIBUTION

Site diary supplied as prepared by Reginald Igbayue (Project Manager). The diary covers activities through 2 September; GPS photographs show asphalt works on 3 September and finished surfaces on 4 September. These sources have different reporting periods.

Quality test results, as-built measurements, signed completion certificates and post-rainfall drainage performance verification were not supplied. No claims of certified acceptance or tested flood elimination are made.